

Nortel Networks Certificate of Compatibility

Nortel Networks Developer Program is pleased to verify that:

HP DL380 G3
a product of
Hewlett-Packard

has successfully met the Nortel Networks standards for compatibility testing in Nortel Networks' laboratory environment with the Nortel Networks communications platform listed below.*

Successful Completion of Compatibility Test Audit on **July 14, 2003***

Developer Product:

HP DL380 G3

Platform:

S/W Rls. Level:

Not Applicable

S/W Patch Rls.

Not Applicable

Nortel Networks Product/Platform:

Symposium Call Center Server 4.2


S/W Patch Rls.

Not Applicable

Compatibility Region: North America

Developer Product may not be available in all countries. Please contact the Developer directly for market availability in your area.

*The Developer Product listed is verified in the Nortel Networks laboratory environment as compatible with the indicated Nortel Networks Product for a term of one (1) year from the date the Compatibility Test Audit was successfully completed as indicated above, until the Developer issues a new version of such Developer Product that incorporates new features or functionality or until Nortel Networks issues a new version of such Nortel Networks Product that incorporates new features or functionality, whichever occurs first. NORTEL NETWORKS MAKES NO REPRESENTATIONS, WARRANTIES OR CONDITIONS WITH RESPECT TO THE DEVELOPER PRODUCT OR THE NORTEL NETWORKS PRODUCT. WITHOUT LIMITING THE GENERALITY OF THE FOREGOING, NORTEL NETWORKS HEREBY EXPRESSLY DISCLAIMS ANY AND ALL REPRESENTATIONS, WARRANTIES OR CONDITIONS OF ANY NATURE WHATSOEVER AS TO THE DEVELOPER PRODUCT AND THE NORTEL NETWORKS PRODUCT INCLUDING WITHOUT LIMITATION THE IMPLIED WARRANTIES OF MERCHANTABILITY, NON INFRINGEMENT OR FITNESS FOR A PARTICULAR PURPOSE AND NORTEL NETWORKS FURTHER SHALL HAVE NO LIABILITY TO DEVELOPER OR ANY OTHER PARTY ARISING FROM OR RELATED IN ANY MANNER TO THIS CERTIFICATE OF COMPATIBILITY.



Configuration Notes for: **HP DL380 G3**

- DL380 Server requires installation of 3rd party PCI card to enable 2nd COM port for Meridian Mail voice prompt provision.

Axxon Computer Corporation - MAP/950 PRO PCI Single 16950 RS232 I/O Card

- Custom INF file must be downloaded and utilized during installation process.

<<<http://www.softio.com/ic0560kb/MSPORTS.INF>>>

- Utilization of CallPilot for voice prompt services does not require 2nd COM port.